

PREMIER SIPS SPLINE BASICS

Premier SIPS are connected by splines.


There are three basic types of spline connections:

- Type S
- Type I
- Type L


SPLINE CONSIDERATIONS FOR DESIGN PROFESSIONALS:

- If splines are simply acting as a connection between panels, the “Type S” spline meets this requirement while eliminating thermal bridging.
- If the purpose of the spline is also to provide additional structural support, “Type I” or “Type L” splines can be used.
- Determination of proper spline for the application can be determined by referring to Premier SIPS Load Charts.

TYPE S SPLINE



TYPE I SPLINE



TYPE L SPLINE

